

## KMK's Portable Hard Disk Drive Destruction Process in 3 steps:



### Step 1:

The Portable Hydraulic Punch provides destruction of your hard-drives under your witness. Ready to operate within minutes KMK trained operatives will operate the equipment and only require access to a power source (220v).

After each HDD has had its serial number/asset tag recorded (optional) the units are individually placed into the hydraulic punch.



### Step 2:

HDD's are inserted in the hydraulic punch one-by one

The door is closed and this allows the remote control to begin the punch process. (As a safeguard to prevent unintentional harm, the door must be closed or the punch cannot operate).

Each destruction takes 30-40 seconds.



### Step 3:

The hydraulic punch bends the HDD out of shape and punches out a significant hole in each HDD. This completely destroys the disks and renders data unrecoverable.

HDD that have been processed are stored securely in a suitable container for transport back to KMK Metals Recycling. Here the HDD are batched together with similar grade metals and sent for refining to dedicated metals smelters.

### Final Result:

